



Errata

**NFPA 70<sup>®</sup>**

***National Electrical Code<sup>®</sup>***

**2014 Edition**

**Reference:** 517.18(A), Exception No. 2 and 690.13(A) Exception

**Errata No.:** 70-14-4

The National Electrical Code Correlating Committee notes the following errors in the 2014 edition of NFPA 70, *National Electrical Code*.

1. 517.18(A), Exception No. 2. Change second cross reference from 517.18(B)(2) to 517.10(B)(2).
2. 690.13(A), Exception. Change cross reference from 690.31(F) to 690.31(G).

**Issue Date:** July 29, 2014

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see [www.nfpa.org/codelist](http://www.nfpa.org/codelist))

Copyright © 2014 All Rights Reserved  
NATIONAL FIRE PROTECTION ASSOCIATION